

Bridge Inspection Report

A5984
I-49 SB L Benton
over
CORD 831-G



Inspection Date:

Inspected By:

Inspection Type(s):

TABLE OF CONTENTS

	PAGE NUMBER
LOCATION MAP	3
NATIONAL BRIDGE INVENTORY	8
ELEMENTS	9
PICTURES	11
SKETCHES	13

Inspector:


Structure Number: A5984

Inspection Date:

Facility Carried: I-49 SB L Benton

Bridge Inspection Report

Location Map



Latitude: 36.40420

Longitude: -94.19798

Inspector:


Structure Number: A5984

Inspection Date:

Facility Carried: I-49 SB L Benton

Bridge Inspection Report

Location Map



Latitude: 36.40420

Longitude: -94.19798

Inspector:


Structure Number: A5984

Inspection Date:

Facility Carried: I-49 SB L Benton

Bridge Inspection Report

Location Map



Latitude: 36.40420

Longitude: -94.19798

Inspector:


Inspection Date:

Structure Number: A5984

Facility Carried: I-49 SB L Benton

Bridge Inspection Report

Location Map



Latitude: 36.40420

Longitude: -94.19798

Inspector:

Inspection Date:

Structure Number: A5984

Facility Carried: I-49 SB L Benton

Bridge Inspection Report

Executive Summary

Logged South to North.

Inspector:

Structure Number: A5984

Inspection Date:

Facility Carried: I-49 SB L Benton

Bridge Inspection Report

National Bridge Inventory

IDENTIFICATION		INSPECTIONS	
(1) STATE CODE	056 - Arkansas	(90) INSPECTION DATE	10/23/2019
(8) STRUCTURE NUMBER	A5984	(91) DESIGNATED INSPECTION FREQUENCY	24
(5) INV. ROUTE (ON/UNDER)	1 1 1 49 3	(92) CRITICAL FEATURE INSPECTION	(93) CFI DATE
(2) HIGHWAY AGENCY	09 (3) COUNTY CODE 007	A. FRACTURE CRITICAL DETAIL	N
(4) PLACE CODE	00000	B. UNDERWATER INSPECTION	N
(6) FEATURES INTERSECTED	CORD 831-G	C. OTHER SPECIAL	N
(7) FACILITY CARRIED	I-49 SB L Benton		
(9) LOCATION	2.25 MI N SH 72		
(11) MILEPOINT 90.110	(12) BASE HIGHWAY NETWORK 1		
(13A) LRS INVENTORY ROUTE	0000049090 (13B) SUBROUTE NUMBER 00		
(16) LATITUDE 36.40420	(17) LONGITUDE -94.19798		
(98A) BORDER BRIDGE CODE			
PERCENT RESPONSIBILITY	(99) BORDER BRIDGE STRUCT		
STRUCTURE TYPE AND MATERIAL		CONDITION	
(43) STRUCTURE TYPE, MAIN		(58) DECK	7
A) KIND OF MATERIAL/DESIGN: 4 - Steel continuous		(59) SUPERSTRUCTURE 6	(60) SUBSTRUCTURE 7
B) TYPE OF DESIGN/CONSTR: 02 - Stringer/Multi-beam or Girder		(61) CHANNEL & CHANNEL PROTECTION	N (62) CULVERT N
(44) STRUCTURE TYPE, APPROACH SPANS			
A) KIND OF MATERIAL/DESIGN: 0 - Other			
B) TYPE OF DESIGN/CONSTR: 00 - Other			
(45) NUMBER OF SPANS IN MAIN 3	(46) NUMBER OF APPROACH 0		
(107) DECK STRUCTURE TYPE 1	(108A) WEARING SURFACE 1		
(108B) DECK MEMBRANE 0	(108C) DECK PROTECTION 1		
AGE OF SERVICE		LOAD RATING AND POSTING	
(27) YEAR BUILT 1989	(106) YEAR RECONSTRUCTED 0000	(31) DESIGN LOAD	5
(42) TYPE OF SERVICE ON 1 UNDER 1		(63) METHOD USED TO DETERMINE OPERATING RATING	1
(28) LANES ON 02 UNDER 02		(64) OPERATING RATING	60.0
(29) AVERAGE DAILY TRAFFIC 47883	(19) BYPASS DETOUR LENGTH 1	(65) METHOD USED TO DETERMINE INVENTORY RATING	1
(30) YEAR OF AVERAGE DAILY TRAFFIC 2014		(66) INVENTORY RATING	36.0
(109) AVERAGE DAILY TRUCK TRAFFIC 1		(70) BRIDGE POSTING	5
		(41) STRUCTURE OPEN/POSTED/CLOSED	A
GEOMETRIC DATA		APPRAISAL	
(48) LENGTH OF MAX SPAN (ft.) 66	(49) STRUCTURE LENGTH (ft.) 181	(67) STRUCTURAL EVALUATION	6
(50) CURB/SIDEWALK WIDTHS (ft.) LEFT 0 RIGHT 0		(68) DECK GEOMETRY	7
(51) BRDG RDWY WIDTH CURB-TO-CURB (ft.) 40.0		(69) UNDERCLEARANCES, VERTICAL & HORIZONTAL	4
(52) DECK WIDTH, OUT-TO-OUT (ft.) 42.8		(71) WATERWAY ADEQUACY	N
(32) APPROACH ROADWAY WIDTH (ft.) 40.0		(72) APPROACH ROADWAY ALIGNMENT	8
(33) BRIDGE MEDIAN 0	(34) SKEW (DEG.) 19	(36) TRAFFIC SAFETY FEATURE	
(35) STRUCTURE FLARED 0	(10) INV RTE, MIN VERT CLEAR (ft.) 99.99	36A) BRIDGE RAILINGS:	1
(47) TOTAL HORIZONTAL CLEARANCE (ft.) 41.0		36B) TRANSITIONS:	0
(53) VERTICAL CLEARANCE OVER BRIDGE ROADWAY (ft.) 99.99		36C) APPROACH GUARDRAIL:	0
(54) VERTICAL UNDER CLEARANCE (ft.) H 26.42		36D) APPROACH GUARDRAIL ENDS:	0
(55) LATERAL UNDER CLEARANCE RIGHT (ft.) H 7.2		(113) SCOUR CRITICAL BRIDGES	N
(56) MIN LATERAL UNDER CLEARANCE (ft.) 0		SUFFICIENCY RATING 89.4	STATUS 0
PROPOSED IMPROVEMENTS		CLASSIFICATION	
(75A) TYPE OF WORK PROPOSED	(75B) WORK DONE BY	(112) NBIS BRIDGE LENGTH	Y
(76) LENGTH OF STRUCTURE IMPROVEMENT (ft.) 0		(104) HIGHWAY SYSTEM OF THE INVENTORY ROUTE	1
(94) BRIDGE IMPROVEMENT COST (\$)	0	(26) FUNCTIONAL CLASSIFICATION OF INVENTORY ROUTE	11
(95) ROADWAY IMPROVEMENT COST (\$)	0	(100) STRAHNET HIGHWAY DESIGNATION	1
(96) TOTAL PROJECT COST	0	(101) PARALLEL STRUCTURE DESIGNATION	L
(97) YEAR OF IMPROVEMENT COST ESTIMATE		(102) DIRECTION OF TRAFFIC	1
(114) FUTURE ADT 21860	(115) YEAR OF FUTURE ADT 2028	(103) TEMP STRUCTURE	
		(105) FEDERAL LANDS HIGHWAYS	0
		(110) DESIGNATED NATIONAL NETWORK	1
		(20) TOLL	3
		(21) MAINTENANCE RESPONSIBILITY	01
		(22) OWNER	01
		(37) HISTORICAL	5
		NAVIGATION DATA	
		(38) NAVIGATION CONTROL	N
		(111) PIER OR ABUTMENT PROTECTION	1
		(39) NAV VERT CLEARANCE (ft.)	0
		(116) MIN NAVIGATION VERT CLEARANCE, VERT LIFT BRIDGE (ft.)	0
		(40) NAV HORIZONTAL CLEARANCE (ft.)	0

Inspector:

Structure Number: A5984

Inspection Date:

Facility Carried: I-49 SB L Benton

Bridge Inspection Report

Element Inspection

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
12 - Reinforced Concrete Deck	1- Ben.	7160	sq. ft.	5312	1848	0	0
	10/23/2019 - WNR & DBM: -The driving surface of the deck has full length longitudinal cracks in both lanes. -The gutters have transverse cracking that correspond with joints in bridge railing. -The wheel paths have light abrasion. -The right gutter has moderate dirt and debris accumulation.						
1120 - Efflorescence/Rust Staining		60		0	60	0	0
1130 - Cracking (RC and Other)		348		0	348	0	0
1190 - Abrasion/Wear (PSC/RC)		1440		0	1440	0	0
107 - Steel Open Girder/Beam	1- Ben.	1074	ft.	1057	9	8	0
	10/23/2019 - WNR & DBM: -The webs of the girders over the abutments have corrosion with initial section loss at the deck haunch juncture. -Span #2, Girder #2 has one loose bolt in the vertical splice plate. -Span #3, girders #4 and #6 have a loose bolt in the bottom flange splice plate connection. -The majority of the paint system is oxidized.						
1000 - Corrosion		17		0	9	8	0
515 - Steel Protective Coating		7904	sq. ft.	7887	0	2	15
3440 - Effectiveness (Steel Protective Coatings)		17		0	0	2	15
205 - Reinforced Concrete Column	1- Ben.	4	each	4	0	0	0
	10/23/2019 - WNR & DBM: -No noteworthy deficiencies at this inspection.						
215 - Reinforced Concrete Abutment	1- Ben.	92	ft.	60	32	0	0
	10/23/2019 - WNR & DBM: -The top of the abutment backwalls have transverse cracking at random spacing and shallow spalling along the expansion joint assemblies. -Abutment #1 adjacent to bearing #6 has softball-sized delaminated area in the vertical face of breastwall.						
1080 - Delamination/Spall/Patched Area		16		0	16	0	0
1130 - Cracking (RC and Other)		16		0	16	0	0
234 - Reinforced Concrete Pier Cap	1- Ben.	84	ft.	84	0	0	0
	10/23/2019 - WNR & DBM: -No noteworthy deficiencies at this inspection.						
302 - Compression Joint Seal	1- Ben.	92	ft.	31	50	11	0
	10/23/2019 - WNR & DBM: -Compression joint seals have deterioration with cracking. -Abutment #2 compression joint seal has dirt and debris impaction randomly throughout joint that has caused the seals to separate from the assemblies allowing water to leak onto the superstructure.						

Inspector:

Structure Number: A5984

Inspection Date:

Facility Carried: I-49 SB L Benton

Bridge Inspection Report

Element Inspection

2310 - Leakage		35		0	35	0	0
2340 - Seal Cracking		15		0	15	0	0
7000 - Damage		11		0	0	11	0
310 - Elastomeric Bearing	1- Ben.	12	each	12	0	0	0
10/23/2019 - WNR & DBM: -No noteworthy deficiencies at this inspection.							
311 - Movable Bearing	1- Ben.	12	each	1	6	5	0
10/23/2019 - WNR & DBM: -The bearings over abutments have corrosion with flaking rust between the rocker devices and the masonry plates. -Abutment #1 bearing #1 left side of rocker does not make contact with masonry plate. -abutment #1 bearings #5 & #6 are the worst cases at abutment #1. -Abutment #2, bearing #3 has movement under live load where the beam is attached to the bearing device. -Bearings have rust staining in locations indicating wear due to fretting.							
1000 - Corrosion		11		0	6	5	0
515 - Steel Protective Coating		36	sq. ft.	7	0	6	23
3440 - Effectiveness (Steel Protective Coatings)		29		0	0	6	23
321 - Reinforced Concrete Approach Slab	1- Ben.	2016	sq. ft.	1385	520	111	0
10/23/2019 - WNR & DBM: -The approach slabs have wide longitudinal, transverse and diagonal cracking with light abrasion in the wheel paths.							
1130 - Cracking (RC and Other)		155		0	44	111	0
1190 - Abrasion/Wear (PSC/RC)		476		0	476	0	0
331 - Reinforced Concrete Bridge Railing	1- Ben.	362	ft.	334	28	0	0
10/23/2019 - WNR & DBM: -The concrete bridge railing has vertical cracks in random locations. -The bases of bridge railing has light scaling in several locations.							
1130 - Cracking (RC and Other)		28		0	28	0	0

Inspector:

Inspection Date:

Structure Number: A5984

Facility Carried: I-49 SB L Benton

Bridge Inspection Report

Pictures

PHOTO 1

Description

PHOTO 1

Description

Inspector:

Inspection Date:

Structure Number: A5984

Facility Carried: I-49 SB L Benton

Bridge Inspection Report

Pictures

PHOTO 2

Description

PHOTO 3

Description

Inspector:

Inspection Date:

Structure Number: A5984

Facility Carried: I-49 SB L Benton

Bridge Inspection Report

Sketches

Inspector:

Structure Number: A5984

Inspection Date:

Facility Carried: I-49 SB L Benton

Bridge Inspection Report

Maintenance Needs

Date Reported: 10/11/2011 12:00:00 AM

Priority: D - Routine

Work Code:

Deficiency Description:

Moveable bearings - The moveable bearings over both abutments have corrosion with thick pack rust between the rocker devices and masonry plates.

Bearing #3 over abutment #2 appears to have wear in the bolted connection that attaches the beam to the bearing device. The bearing has significant movement under live load.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Monitor



PHOTO 1 Description Bearings #6 abutment #1 pack rust.

Stage: Monitor



PHOTO 2 Description Abutment #2 bearing #6 flaking rust.

Inspector:

Inspection Date:

Structure Number: A5984

Facility Carried: I-49 SB L Benton

Bridge Inspection Report

Maintenance Needs

Stage: Monitor



PHOTO 3 Description Abutment #2 bearing #2 fretting between rocker and sole plate.

Inspector:

Structure Number: A5984

Inspection Date:

Facility Carried: I-49 SB L Benton

Bridge Inspection Report

Maintenance Needs

Date Reported: 10/11/2011 12:00:00 AM

Priority: G - General/ Preventive maintenance

Work Code:

Deficiency Description:

Superstructure - Span #2, Girder #2 has one loose bolt in the vertical splice plate.
Span #3, Girders #4 and #6 have one loose bolt in the bottom flange splice plate connection.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Monitor




PHOTO 1 Description Span #2 Girder #2 vertical splice plate - loose bolt.

Stage: Monitor




PHOTO 2 Description Span 3, Girder 6 bottom splice plate - loose bolt.

Inspector:

Inspection Date:

Structure Number: A5984

Facility Carried: I-49 SB L Benton

Bridge Inspection Report

Maintenance Needs

Stage: Monitor



PHOTO 3 Description Span #3, Girders #6 have one loose bolt in the bottom flange splice plate connection.

Inspector:

Structure Number: A5984

Inspection Date:

Facility Carried: I-49 SB L Benton

Bridge Inspection Report

Maintenance Needs

Date Reported: 10/11/2011 12:00:00 AM

Priority: D - Routine

Work Code:

Deficiency Description:

Deck expansion joints - Compression joint seals are deteriorated with areas of cracking and dirt and debris impaction that has caused the seals to separate from the assemblies allowing water to leak onto the superstructure.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Monitor



PHOTO 1 Description Dirt and debris in expansion joint assemblies.

Stage: Monitor



PHOTO 2 Description Abutment #1 expansion joint tearing and cracking

Inspector:

Structure Number: A5984

Inspection Date:

Facility Carried: I-49 SB L Benton

Bridge Inspection Report

Maintenance Needs

Date Reported: 10/19/2017

Priority: D - Routine

Work Code:

Deficiency Description:

Deck / Approach slabs - The driving surface of the deck has sealable longitudinal and transverse cracking in all spans. The North and South approach slabs have sealable longitudinal, transverse and random cracking.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Monitor



PHOTO 1 Description Longitudinal and transverse cracking in south approach slab

Stage: Open



PHOTO 2 Description North approach slab-Transverse cracking.

Inspector:

Inspection Date:

Structure Number: A5984

Facility Carried: I-49 SB L Benton

Bridge Inspection Report

Maintenance Needs

Stage: Open



PHOTO 3 Description South approach slab-Longitudinal cracking.

Stage: Open



PHOTO 4 Description Deck has sealable cracking in all spans.

Inspector:

Structure Number: A5984

Inspection Date:

Facility Carried: I-49 SB L Benton

Bridge Inspection Report

Maintenance Needs

Date Reported: 10/19/2017

Priority: G - General/ Preventive maintenance

Work Code:

Deficiency Description:

Deck - The right gutter has moderate dirt and debris accumulation.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Assigned



PHOTO 1 Description Right gutterline dirt and debris accumulation

Stage: Open



PHOTO 2 Description Dirt and debris in right gutter.