




Bridge #01534(Routine)

Us-70/Sec-17/L6.61 over Channey Slough

Location: 1.0 Miles West Jct Sh 17

Team Lead: Joel Davis **Inspection Date:** October 11, 2016

1.0 Miles West Jct Sh 17



34.83961, -91.26170



Bridge #01534(Routine)
Us-70/Sec-17/L6.61 over Channey Slough

Location: 1.0 Miles West Jct Sh 17

Team Lead: Joel Davis Inspection Date: October 11, 2016

IDENTIFICATION	
(1) State Names	Arkansas
(8) Structure Number	01534
(5) Inventory Route	70
(2) Highway Agency District	01
(3) County Code	95-Monroe County, Arkansas
(4) Place Code	0
(6) Features Intersected	CHANY SLOUGH
(7) Facility Carried	US 70
(9) Location	1.0 M W JCT SH 17
(11) Mile Point	6.61 mi
(12) Base Highway Network	No
(13) LRS Inventory Rte & Subrte	0000000000
(16) Latitude	34.83961
(17) Longitude	-91.2617
(98) Border Bridge State Code	
(99) Border Bridge Structure No.	
STRUCTURE TYPE AND MATERIAL	
(43) Main Structure Type	14
Material	1-Concrete
Type	4-Tee beam
(44) Approach Structure Type	00
Material	0-Other
Type	0-Other
(45) No. of Spans in Main Unit	2
(46) No. of Approach Spans	0
(107) Deck Structure Type	1-Concrete Cast-in-Place
(108) Wearing Surface/Protective System	
Type of Wearing Surface	6-Bituminous
Type of Membrane	0-None
Type of Deck Protection	0-None
AGE AND SERVICE	
(27) Year Built	1930
(106) Year Reconstructed	0
(42) Type of Service	15
On	1-Highway
Under	5-Waterway
(28) Lane	
On	2
Under	0
(29) Average Daily Traffic	2600
(30) Year of ADT	2014
(109) Truck ADT	19 %
(19) Bypass, Detour Length	4 mi
GEOMETRIC DATA	
(48) Length of Maximum Span	34 ft
(49) Structure Length	69 ft
(50) Curb or Sidewalk Width	
Left	0.5 ft
Right	0.5 ft
(51) Bridge Roadway Width Curb to Curb	26.9 ft
(52) Deck Width Out to Out	30 ft
(32) Approach Roadway Width (W/Shoulders)	37.1 ft
(33) Bridge Median	0-No median
(34) Skew	0 Deg
(35) Structure Flared	No flare
(10) Inventory Route Min Vert Clear	99.99 ft
(47) Inventory Route Total Horiz Clear	27.9 ft
(53) Min Vert Clear Over Bridge Rdwy	99.99 ft
(54) Min Vert Underclear	0 ft
Ref:	
(55) Min Lat Underclear RT	99.9 ft
Ref:	
(56) Min Lat Underclear LT	0 ft
NAVIGATION DATA	
(38) Navigation Control	0-No navigation control on water
(111) Pier Protection	1-Navigation protection not requ
(39) Navigation Vertical Clearance	0 ft
(116) Vert-Lift Bridge Nav Min Vert Clear	0 ft
(40) Navigation Horizontal Clearance	0 ft

CLASSIFICATION	
(112) NBIS Bridge Length	Y
(104) Highway System	0
(26) Functional Class	7-Rural Major Collector
(100) Defense Highway	0-The inventory route is not a S
(101) Parallel Structure	N-No parallel structure exists.
(102) Direction of Traffic	2 - way traffic
(103) Temporary Structure	
(105) Federal Lands Highways	0-N/A
(110) Designated National Network	1-The inventory route is part of the
(20) Toll	3-On free road. The structure is toll-
(21) Maintain	1-State Highway Agency
(22) Owner	1-State Highway Agency
(37) Historical Significance	5-Bridge is not eligible for the NRHP
CONDITION	
(58) Deck	7
(59) Superstructure	7
(60) Substructure	7
(61) Channel & Channel Protection	6
(62) Culverts	N
LOAD RATING AND POSTING	
(31) Design Load	2-M 13.5 / H 15
(63) Operating Rating Method	1
(64) Operating Rating	
Type	1-Load Factor(LF)
Rating	46
(65) Inventory Rating Method	1-Load Factor(LF)
(66) Inventory Rating	
Type	2
Rating	28
(70) Bridge Posting	5-Equal to or above legal loads
(41) Structure Open/Posted/Closed	A-Open, no restriction
APPRAISAL	
(67) Structural Evaluation	6
(68) Deck Geometry	3
(69) Clearances, Vertical/Horizontal	N
(71) Waterway Adequacy	8
(72) Approach Roadway Alignment	8
(36) Traffic Safety Features	0000
A) Bridge Railings	0-Inspected feature does not meet cur
B) Transitions	0-Inspected feature does not meet cur
C) Approach Guardrail	0-Inspected feature does not meet cur
D) Approach Guardrail Ends	0-Inspected feature does not meet cur
(113) Scour Critical Bridges	5-Bridge foundations determined to be
PROPOSED IMPROVEMENTS	
(75) Type of Work	
(76) Length of Structure Improvement	0 ft
(94) Bridge Improvement Cost	\$ 0
(95) Roadway Improvement Cost	\$ 0
(96) Total Project Cost	\$ 0
(97) Year of Improvement Cost Estimate	
(114) Future ADT	1167
(115) Year of Future ADT	2028
INSPECTIONS	
(90) Inspection Date	
(91) Frequency	24 Months
(92) Critical Feature Inspection	Done Freq. (Mon) Date
A: Fracture Critical Detail	No 24
B: Underwater Inspection	No 0
C: Other Special Inspection	No 0

Team Lead: Joel Davis, **Inspection Date:** October 11, 2016

ELEM	DESCRIPTION	UNITS	TOTAL	CS1	CS2	CS3	CS4
16	Reinforced Concrete Top Flange	SF	2070	2070	0	0	0
510	Wearing Surfaces	SF	1863	1863	0	0	0
(16)							
SPAN #1 LEFT CURB HAS AREAS OF HEAVY SCALING.							
110	Reinforced Concrete Open Girder/Beam	LF	345	332	10	3	0
1080	Delamination/Spall/Patched Area	LF	10	0	10	0	0
1090	Exposed Rebar	LF	3	0	0	3	0
(110)							
SPAN GDR BENT DEFICIENCY							
1	3	MID-SPAN 3 3"-4" POP-OFF SPALLS WITH EXPOSED REBAR.					
1	5	2	SPALL ON WEB WITH EXPOSED SECONDARY REBAR				
2	1	3	SPALL LT SIDE WITH 3- 6" PIECES OF REBAR EXPOSED.				
215	Reinforced Concrete Abutment	LF	64	0	64	0	0
6000	Scour	LF	64	0	64	0	0
(215)							
ABUTMENT #1,2 UNDERMINED 2' EXPOSING ALL PILES							
227	Reinforced Concrete Pile	EA	15	15	0	0	0
234	Reinforced Concrete Pier Cap	LF	78	77	0	1	0
1090	Exposed Rebar	LF	1	0	0	1	0
(234)							
BENT #2 RIGHT END SPALLED WITH EXPOSED REBAR.							
331	Reinforced Concrete Bridge Railing	LF	138	137	0	1	0
1090	Exposed Rebar	LF	1	0	0	1	0
(331)							
SPAN #2 LEFT SIDE HAS MINOR COLLISION DAMAGE WITH 1'+- EXPOSED REBAR.							



Bridge #01534(Routine)

Us-70/Sec-17/L6.61 over Channey Slough

Location: 1.0 Miles West Jct Sh 17

Team Lead: Joel Davis **Inspection Date:** October 11, 2016



Bridge #01534(Routine)

Us-70/Sec-17/L6.61 over Channey Slough

Location: 1.0 Miles West Jct Sh 17

Team Lead: Joel Davis **Inspection Date:** October 11, 2016

Maintenance Needs



Bridge #01534(Routine)
Us-70/Sec-17/L6.61 over Channey Slough

Location: 1.0 Miles West Jct Sh 17

Team Lead: Joel Davis Inspection Date: October 11, 2016

Inspection Comments

-

Deck Notes

SPAN #1 LEFT CURB HAS AREAS OF HEAVY SCALING.
BRIDGE RAIL-SPAN #2 LEFT SIDE HAS MINOR COLLISION DAMAGE WITH 1'+- EXPOSED REBAR.

Superstructure Notes

SPAN GDR BENT DEFICIENCY 1 3 MID-SPAN 3, 3"-4" POP-OFF SPALLS WITH EXPOSED
REBAR. 1 5 2 SPALL ON WEB WITH EXPOSED SECONDARY REBAR 2 1 3 SPALL LT SIDE WITH 3,
6" PIECES OF REBAR EXPOSED.

Substructure Notes

ABUTMENT #1,2 UNDERMINED 2' EXPOSING ALL PILESCAP-BENT #2 RIGHT END SPALLED WITH EXPOSED REBAR.