

Bridge Inspection Report

B7171
I-555-02 NB
over
Ditch # 1, & 47



Inspection Date:

Inspected By:

Inspection Type(s):

TABLE OF CONTENTS

	PAGE NUMBER
LOCATION MAP	3
NATIONAL BRIDGE INVENTORY	8
ELEMENTS	9
PICTURES	10
SKETCHES	13

Inspector:


Structure Number: B7171

Inspection Date:

Facility Carried: I-555-02 NB

Bridge Inspection Report

Location Map



Latitude: 35.51415

Longitude: -90.39648

Inspector:


Structure Number: B7171

Inspection Date:

Facility Carried: I-555-02 NB

Bridge Inspection Report

Location Map



Latitude: 35.51415

Longitude: -90.39648

Inspector:


Structure Number: B7171

Inspection Date:

Facility Carried: I-555-02 NB

Bridge Inspection Report

Location Map



Latitude: 35.51415

Longitude: -90.39648

Inspector:


Structure Number: B7171

Inspection Date:

Facility Carried: I-555-02 NB

Bridge Inspection Report

Location Map



Latitude: 35.51415

Longitude: -90.39648

Inspector:

Inspection Date:

Structure Number: B7171

Facility Carried: I-555-02 NB

Bridge Inspection Report

Executive Summary

Inspector:

Structure Number: B7171

Inspection Date:

Facility Carried: I-555-02 NB

Bridge Inspection Report

National Bridge Inventory

IDENTIFICATION		INSPECTIONS	
(1) STATE CODE	056 - Arkansas	(90) INSPECTION DATE	04/29/2019
(8) STRUCTURE NUMBER	B7171	(91) DESIGNATED INSPECTION FREQUENCY	24
(5) INV. ROUTE (ON/UNDER)	1 1 1 555 1	(92) CRITICAL FEATURE INSPECTION	(93) CFI DATE
(2) HIGHWAY AGENCY	10 (3) COUNTY CODE 111	A. FRACTURE CRITICAL DETAIL	N
(4) PLACE CODE	00000	B. UNDERWATER INSPECTION	N
(6) FEATURES INTERSECTED	Ditch # 1, & 47	C. OTHER SPECIAL	N
(7) FACILITY CARRIED	I-555-02 NB		
(9) LOCATION	2.11 M S of Jct. SH 75		
(11) MILEPOINT 11.53	(12) BASE HIGHWAY NETWORK 0		
(13A) LRS INVENTORY ROUTE	0000000000 (13B) SUBROUTE NUMBER 00		
(16) LATITUDE 35.51415	(17) LONGITUDE -90.39648		
(98A) BORDER BRIDGE CODE			
PERCENT RESPONSIBILITY	(99) BORDER BRIDGE STRUCT		
STRUCTURE TYPE AND MATERIAL		CONDITION	
(43) STRUCTURE TYPE, MAIN		(58) DECK	8
A) KIND OF MATERIAL/DESIGN: 4 - Steel continuous		(59) SUPERSTRUCTURE	9 (60) SUBSTRUCTURE 8
B) TYPE OF DESIGN/CONSTR: 02 - Stringer/Multi-beam or Girder		(61) CHANNEL & CHANNEL PROTECTION	7 (62) CULVERT N
(44) STRUCTURE TYPE, APPROACH SPANS			
A) KIND OF MATERIAL/DESIGN: 0 - Other			
B) TYPE OF DESIGN/CONSTR: 00 - Other			
(45) NUMBER OF SPANS IN MAIN 8	(46) NUMBER OF APPROACH 0		
(107) DECK STRUCTURE TYPE 1	(108A) WEARING SURFACE 1		
(108B) DECK MEMBRANE 0	(108C) DECK PROTECTION 1		
AGE OF SERVICE		LOAD RATING AND POSTING	
(27) YEAR BUILT 2011	(106) YEAR RECONSTRUCTED 0000	(31) DESIGN LOAD	A
(42) TYPE OF SERVICE ON 1 UNDER 5		(63) METHOD USED TO DETERMINE OPERATING RATING	1
(28) LANES ON 02 UNDER 00		(64) OPERATING RATING	60.0
(29) AVERAGE DAILY TRAFFIC 12000	(19) BYPASS DETOUR LENGTH 2	(65) METHOD USED TO DETERMINE INVENTORY RATING	1
(30) YEAR OF AVERAGE DAILY TRAFFIC 2014		(66) INVENTORY RATING	36.0
(109) AVERAGE DAILY TRUCK TRAFFIC 24		(70) BRIDGE POSTING	5
		(41) STRUCTURE OPEN/POSTED/CLOSED	A
GEOMETRIC DATA		APPRAISAL	
(48) LENGTH OF MAX SPAN (ft.) 60	(49) STRUCTURE LENGTH (ft.) 422.3	(67) STRUCTURAL EVALUATION	8
(50) CURB/SIDEWALK WIDTHS (ft.) LEFT 0 RIGHT 0		(68) DECK GEOMETRY	7
(51) BRDG RDWY WIDTH CURB-TO-CURB (ft.) 40.0		(69) UNDERCLEARANCES, VERTICAL & HORIZONTAL	N
(52) DECK WIDTH, OUT-TO-OUT (ft.) 43.2		(71) WATERWAY ADEQUACY	7
(32) APPROACH ROADWAY WIDTH (ft.) 40.0		(72) APPROACH ROADWAY ALIGNMENT	8
(33) BRIDGE MEDIAN 1	(34) SKEW (DEG.) 20	(36) TRAFFIC SAFETY FEATURE	
(35) STRUCTURE FLARED 0	(10) INV RTE, MIN VERT CLEAR (ft.) 99.99	36A) BRIDGE RAILINGS:	1
(47) TOTAL HORIZONTAL CLEARANCE (ft.) 40.8		36B) TRANSITIONS:	1
(53) VERTICAL CLEARANCE OVER BRIDGE ROADWAY (ft.) 99.99		36C) APPROACH GUARDRAIL:	1
(54) VERTICAL UNDER CLEARANCE (ft.) N 0		36D) APPROACH GUARDRAIL ENDS:	1
(55) LATERAL UNDER CLEARANCE RIGHT (ft.) N 99.9		(113) SCOUR CRITICAL BRIDGES	5
(56) MIN LATERAL UNDER CLEARANCE (ft.) 0		SUFFICIENCY RATING	96.3 STATUS 0
PROPOSED IMPROVEMENTS		CLASSIFICATION	
(75A) TYPE OF WORK PROPOSED	(75B) WORK DONE BY	(112) NBIS BRIDGE LENGTH	Y
(76) LENGTH OF STRUCTURE IMPROVEMENT (ft.) 0		(104) HIGHWAY SYSTEM OF THE INVENTORY ROUTE	1
(94) BRIDGE IMPROVEMENT COST (\$)	0	(26) FUNCTIONAL CLASSIFICATION OF INVENTORY ROUTE	01
(95) ROADWAY IMPROVEMENT COST (\$)	0	(100) STRAHNET HIGHWAY DESIGNATION	1
(96) TOTAL PROJECT COST	0	(101) PARALLEL STRUCTURE DESIGNATION	R
(97) YEAR OF IMPROVEMENT COST ESTIMATE		(102) DIRECTION OF TRAFFIC	1
(114) FUTURE ADT 8750	(115) YEAR OF FUTURE ADT 2029	(103) TEMP STRUCTURE	
		(105) FEDERAL LANDS HIGHWAYS	0
		(110) DESIGNATED NATIONAL NETWORK	1
		(20) TOLL	3
		(21) MAINTENANCE RESPONSIBILITY	01
		(22) OWNER	01
		(37) HISTORICAL	4
		NAVIGATION DATA	
		(38) NAVIGATION CONTROL	0
		(111) PIER OR ABUTMENT PROTECTION	5
		(39) NAV VERT CLEARANCE (ft.)	0
		(116) MIN NAVIGATION VERT CLEARANCE, VERT LIFT BRIDGE (ft.)	0
		(40) NAV HORIZONTAL CLEARANCE (ft.)	0

Inspector:

Structure Number: B7171

Inspection Date:

Facility Carried: I-555-02 NB

Bridge Inspection Report

Element Inspection

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
12 - Reinforced Concrete Deck	1- Ben.	18233	sq. ft.	15306	2816	111	0
1120 - Efflorescence/Rust Staining		111		0	0	111	0
1130 - Cracking (RC and Other)		2816		0	2816	0	0
107 - Steel Open Girder/Beam	1- Ben.	2100	ft.	2100	0	0	0
515 - Steel Protective Coating		20314	sq. ft.	20314	0	0	0
215 - Reinforced Concrete Abutment	1- Ben.	129	ft.	128	0	1	0
1120 - Efflorescence/Rust Staining		1		0	0	1	0
225 - Steel Pile	1- Ben.	42	each	36	6	0	0
1000 - Corrosion		6		0	6	0	0
515 - Steel Protective Coating		28487	sq. ft.	23739	4748	0	0
3440 - Effectiveness (Steel Protective Coatings)		4748		0	4748	0	0
234 - Reinforced Concrete Pier Cap	1- Ben.	305	ft.	305	0	0	0
300 - Strip Seal Expansion Joint	1- Ben.	90	ft.	45	45	0	0
2350 - Debris Impaction		45		0	45	0	0
310 - Elastomeric Bearing	1- Ben.	45	each	45	0	0	0
321 - Reinforced Concrete Approach Slab	1- Ben.	2103	sq. ft.	1880	0	223	0
1130 - Cracking (RC and Other)		223		0	0	223	0
331 - Reinforced Concrete Bridge Railing	1- Ben.	840	ft.	556	284	0	0
1130 - Cracking (RC and Other)		284		0	284	0	0

Inspector:

Inspection Date:

Structure Number: B7171

Facility Carried: I-555-02 NB

Bridge Inspection Report

Pictures

PHOTO 1

Description

PHOTO 1

Description

Inspector:

Inspection Date:

Structure Number: B7171

Facility Carried: I-555-02 NB

Bridge Inspection Report

Pictures

PHOTO 2

Description

PHOTO 2

Description

Inspector:

Inspection Date:

Structure Number: B7171

Facility Carried: I-555-02 NB

Bridge Inspection Report

Pictures

PHOTO 2

Description

PHOTO 3

Description

Inspector:

Inspection Date:

Structure Number: B7171

Facility Carried: I-555-02 NB

Bridge Inspection Report

Sketches

Inspector:

Structure Number: B7171

Inspection Date:

Facility Carried: I-555-02 NB

Bridge Inspection Report

Maintenance Needs

Date Reported: 04/20/2017

Priority: D - Routine

Work Code:

Deficiency Description:

Right Asphalt Shoulder 10ft. from end of Concrete Approach Gutter has a 1ft. x 5ft. x 1.5ft. deep hole in asphalt and shoulder is eroded due to roadway runoff.

Work Description:

Date Repairs Completed:

Maintenance Comments:

to Poinsett Co Crew for review

Date Reported: 04/29/2019

Priority: D - Routine

Work Code:

Deficiency Description:

Compression seals at bents 1 & 9 are partially filled with dirt & debris.

Work Description:

Date Repairs Completed:

Maintenance Comments:
