

Inspector:

Structure Number: 02270

Inspection Date:

Facility Carried: US 278 - 05 -17.92

Bridge Inspection Report

Element Inspection

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
12 - Reinforced Concrete Deck	1- Ben.	3016	sq. ft.	3016			
	asphalt overlay on deck 3.5 inch 2016 asphalt at joints breaking up typ. all joints 459 sqft.						
510 - Wearing Surfaces		2704	sq. ft.	2245		459	
110 - Reinforced Concrete Open Girder/Beam	1- Ben.	520	ft.	520			
215 - Reinforced Concrete Abutment	1- Ben.	76	ft.	76			
227 - Reinforced Concrete Pile	1- Ben.	10	each	10			
234 - Reinforced Concrete Pier Cap	1- Ben.	108	ft.	108			
311 - Movable Bearing	1- Ben.	25	each	0	0	25	0
	bearings were repaired and some sole plates replaced and painted in 2003. 2016 ---90% paint loss and some rusting						
1000 - Corrosion		25				25	
313 - Fixed Bearing	1- Ben.	5	each	0	0	5	0
	bearings were repaired and some sole plates replaced and painted in 2003. 2016---90%paint loss and some rust						
1000 - Corrosion		5				5	
330 - Metal Bridge Railing	1- Ben.	208	ft.	0	0	208	0
	Railing on bridge has 90% paint loss						
1000 - Corrosion		208				208	