



Note: No overlay on bridge deck.





Alleged “shear cracks”. ?