

Bridge Inspection Report

01570
US 82 S-7 LM 2.89
over
CANNON CREEK



Inspection Date:

Inspected By:

Inspection Type(s):

TABLE OF CONTENTS

	PAGE NUMBER
LOCATION MAP	3
NATIONAL BRIDGE INVENTORY	6
ELEMENTS	7
PICTURES	8
SKETCHES	9

Inspector:


Structure Number: 01570

Inspection Date:

Facility Carried: US 82 S-7 LM 2.89

Bridge Inspection Report

Location Map



Latitude: 33.11540

Longitude: -92.31402

Inspector:


Structure Number: 01570

Inspection Date:

Facility Carried: US 82 S-7 LM 2.89

Bridge Inspection Report

Location Map



Latitude: 33.11540

Longitude: -92.31402

Inspector:

Inspection Date:

Structure Number: 01570

Facility Carried: US 82 S-7 LM 2.89

Bridge Inspection Report

Executive Summary

Inspector:

Structure Number: 01570

Inspection Date:

Facility Carried: US 82 S-7 LM 2.89

Bridge Inspection Report

National Bridge Inventory

IDENTIFICATION		INSPECTIONS	
(1) STATE CODE	056 - Arkansas	(90) INSPECTION DATE	06/18/2018
(8) STRUCTURE NUMBER	01570	(91) DESIGNATED INSPECTION FREQUENCY	24
(5) INV. ROUTE (ON/UNDER)	1 2 1 82 0	(92) CRITICAL FEATURE INSPECTION	(93) CFI DATE
(2) HIGHWAY AGENCY	07 (3) COUNTY CODE 139	A. FRACTURE CRITICAL DETAIL	N
(4) PLACE CODE	00000	B. UNDERWATER INSPECTION	N
(6) FEATURES INTERSECTED	CANNON CREEK	C. OTHER SPECIAL	N
(7) FACILITY CARRIED	US 82 S-7 LM 2.89		
(9) LOCATION	2.90 MI E OF STRONG		
(11) MILEPOINT 2.899	(12) BASE HIGHWAY NETWORK 1		
(13A) LRS INVENTORY ROUTE	0000082070 (13B) SUBROUTE NUMBER 00		
(16) LATITUDE	33.11540 (17) LONGITUDE -92.31402		
(98A) BORDER BRIDGE CODE			
PERCENT RESPONSIBILITY	(99) BORDER BRIDGE STRUCT		
STRUCTURE TYPE AND MATERIAL		CONDITION	
(43) STRUCTURE TYPE, MAIN		(58) DECK	8
A) KIND OF MATERIAL/DESIGN: 1 - Concrete		(59) SUPERSTRUCTURE	8 (60) SUBSTRUCTURE 8
B) TYPE OF DESIGN/CONSTR: 01 - Slab		(61) CHANNEL & CHANNEL PROTECTION	7 (62) CULVERT N
(44) STRUCTURE TYPE, APPROACH SPANS			
A) KIND OF MATERIAL/DESIGN: 0 - Other			
B) TYPE OF DESIGN/CONSTR: 00 - Other			
(45) NUMBER OF SPANS IN MAIN	3 (46) NUMBER OF APPROACH		
(107) DECK STRUCTURE TYPE	1 (108A) WEARING SURFACE		
(108B) DECK MEMBRANE	0 (108C) DECK PROTECTION		
AGE OF SERVICE		LOAD RATING AND POSTING	
(27) YEAR BUILT	1931 (106) YEAR RECONSTRUCTED	(31) DESIGN LOAD	5
(42) TYPE OF SERVICE	ON 1 UNDER 5	(63) METHOD USED TO DETERMINE OPERATING RATING	1
(28) LANES	ON 02 UNDER 00	(64) OPERATING RATING	60.0
(29) AVERAGE DAILY TRAFFIC	2800 (19) BYPASS DETOUR LENGTH	(65) METHOD USED TO DETERMINE INVENTORY RATING	1
(30) YEAR OF AVERAGE DAILY TRAFFIC	2014	(66) INVENTORY RATING	36.0
(109) AVERAGE DAILY TRUCK TRAFFIC	1	(70) BRIDGE POSTING	5
		(41) STRUCTURE OPEN/POSTED/CLOSED	A
GEOMETRIC DATA		APPRAISAL	
(48) LENGTH OF MAX SPAN (ft.)	35 (49) STRUCTURE LENGTH (ft.)	(67) STRUCTURAL EVALUATION	8
(50) CURB/SIDEWALK WIDTHS (ft.)	LEFT 0 RIGHT 0	(68) DECK GEOMETRY	7
(51) BRDG RDWY WIDTH CURB-TO-CURB (ft.)	44.0	(69) UNDERCLEARANCES, VERTICAL & HORIZONTAL	N
(52) DECK WIDTH, OUT-TO-OUT (ft.)	46.8	(71) WATERWAY ADEQUACY	8
(32) APPROACH ROADWAY WIDTH (ft.)	27.9	(72) APPROACH ROADWAY ALIGNMENT	8
(33) BRIDGE MEDIAN	0 (34) SKEW (DEG.)	(36) TRAFFIC SAFETY FEATURE	
(35) STRUCTURE FLARED	0 (10) INV RTE, MIN VERT CLEAR (ft.)	36A) BRIDGE RAILINGS:	1
(47) TOTAL HORIZONTAL CLEARANCE (ft.)	45.3	36B) TRANSITIONS:	1
(53) VERTICAL CLEARANCE OVER BRIDGE ROADWAY (ft.)	99.99	36C) APPROACH GUARDRAIL:	1
(54) VERTICAL UNDER CLEARANCE (ft.)	N 0	36D) APPROACH GUARDRAIL ENDS:	1
(55) LATERAL UNDER CLEARANCE RIGHT (ft.)	N 99.9	(113) SCOUR CRITICAL BRIDGES	5
(56) MIN LATERAL UNDER CLEARANCE (ft.)	0	SUFFICIENCY RATING	90.1 STATUS 0
PROPOSED IMPROVEMENTS		CLASSIFICATION	
(75A) TYPE OF WORK PROPOSED	(75B) WORK DONE BY	(112) NBIS BRIDGE LENGTH	Y
(76) LENGTH OF STRUCTURE IMPROVEMENT (ft.)	0	(104) HIGHWAY SYSTEM OF THE INVENTORY ROUTE	1
(94) BRIDGE IMPROVEMENT COST (\$)	0	(26) FUNCTIONAL CLASSIFICATION OF INVENTORY ROUTE	02
(95) ROADWAY IMPROVEMENT COST (\$)	0	(100) STRAHNET HIGHWAY DESIGNATION	0
(96) TOTAL PROJECT COST	0	(101) PARALLEL STRUCTURE DESIGNATION	N
(97) YEAR OF IMPROVEMENT COST ESTIMATE		(102) DIRECTION OF TRAFFIC	2
(114) FUTURE ADT	3305 (115) YEAR OF FUTURE ADT	(103) TEMP STRUCTURE	
	2028	(105) FEDERAL LANDS HIGHWAYS	0
		(110) DESIGNATED NATIONAL NETWORK	1
		(20) TOLL	3
		(21) MAINTENANCE RESPONSIBILITY	01
		(22) OWNER	01
		(37) HISTORICAL	5
		NAVIGATION DATA	
		(38) NAVIGATION CONTROL	0
		(111) PIER OR ABUTMENT PROTECTION	1
		(39) NAV VERT CLEARANCE (ft.)	0
		(116) MIN NAVIGATION VERT CLEARANCE, VERT LIFT BRIDGE (ft.)	0
		(40) NAV HORIZONTAL CLEARANCE (ft.)	0

Inspector:

Structure Number: 01570

Inspection Date:

Facility Carried: US 82 S-7 LM 2.89

Bridge Inspection Report

Element Inspection

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
38 - Reinforced Concrete Slab	1- Ben.	4664	sq. ft.	4349	315	0	0
	Span 1-has 105' of cracks Span 2-has 140' of cracks Span 3-has 70' of cracks						
1130 - Cracking (RC and Other)		315			315		
227 - Reinforced Concrete Pile	1- Ben.	16	each	12	4	0	0
	Bent 3 piles 1-4 have local scour.						
6000 - Scour		4			4		
234 - Reinforced Concrete Pier Cap	1- Ben.	188	ft.	188			
301 - Pourable Joint Seal	1- Ben.	94	ft.	0	94	0	0
2310 - Leakage		47			47		
2320 - Seal Adhesion		47			47		
331 - Reinforced Concrete Bridge Railing	1- Ben.	212	ft.	212			

Inspector:

Inspection Date:

Structure Number: 01570

Facility Carried: US 82 S-7 LM 2.89

Bridge Inspection Report

Pictures

PHOTO 1

Description

Inspector:

Inspection Date:

Structure Number: 01570

Facility Carried: US 82 S-7 LM 2.89

Bridge Inspection Report

Sketches

Inspector:

Structure Number: 01570

Inspection Date:

Facility Carried: US 82 S-7 LM 2.89

Bridge Inspection Report

Maintenance Needs

Date Reported: 06/18/2018

Priority: D - Routine

Work Code:

Deficiency Description:

Local scour hole has developed around piles 1-4 of bent 3.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Open



PHOTO 1 Description