

Bridge Inspection Report

A5020
I 30, WB-13-52.27
over
BLACK CREEK



Inspection Date:

Inspected By:

Inspection Type(s):

Inspector:


Structure Number: A5020

Inspection Date:

Facility Carried: I 30, WB-13-52.27

Bridge Inspection Report

Location Map



Latitude: 33.89021

Longitude: -93.31507

Inspector:


Structure Number: A5020

Inspection Date:

Facility Carried: I 30, WB-13-52.27

Bridge Inspection Report

Location Map



Latitude: 33.89021

Longitude: -93.31507

Inspector:

Structure Number: A5020

Inspection Date:

Facility Carried: I 30, WB-13-52.27

Bridge Inspection Report

Location Map



Latitude: 33.89021

Longitude: -93.31507

Inspector:

Structure Number: A5020

Inspection Date:

Facility Carried: I 30, WB-13-52.27

Bridge Inspection Report

National Bridge Inventory

IDENTIFICATION		INSPECTIONS	
(1) STATE CODE	056 - Arkansas	(90) INSPECTION DATE	02/23/2017
(8) STRUCTURE NUMBER	A5020	(91) DESIGNATED INSPECTION FREQUENCY	24
(5) INV. ROUTE (ON/UNDER)	1 1 1 30 4	(92) CRITICAL FEATURE INSPECTION	(93) CFI DATE
(2) HIGHWAY AGENCY	03 (3) COUNTY CODE 099	A. FRACTURE CRITICAL DETAIL	N
(4) PLACE CODE	00000	B. UNDERWATER INSPECTION	N
(6) FEATURES INTERSECTED	BLACK CREEK	C. OTHER SPECIAL	N
(7) FACILITY CARRIED	I 30, WB-13-52.27		
(9) LOCATION	0.8 MI S CLARK CO LINE		
(11) MILEPOINT 52.270	(12) BASE HIGHWAY NETWORK 0		
(13A) LRS INVENTORY ROUTE	0000000000 (13B) SUBROUTE NUMBER 00		
(16) LATITUDE 33.89021	(17) LONGITUDE -93.31507		
(98A) BORDER BRIDGE CODE			
PERCENT RESPONSIBILITY	(99) BORDER BRIDGE STRUCT		
STRUCTURE TYPE AND MATERIAL		CONDITION	
(43) STRUCTURE TYPE, MAIN		(58) DECK	6
A) KIND OF MATERIAL/DESIGN: 1 - Concrete		(59) SUPERSTRUCTURE	6 (60) SUBSTRUCTURE 6
B) TYPE OF DESIGN/CONSTR: 01 - Slab		(61) CHANNEL & CHANNEL PROTECTION	7 (62) CULVERT N
(44) STRUCTURE TYPE, APPROACH SPANS			
A) KIND OF MATERIAL/DESIGN: 0 - Other			
B) TYPE OF DESIGN/CONSTR: 00 - Other			
(45) NUMBER OF SPANS IN MAIN 7	(46) NUMBER OF APPROACH 0		
(107) DECK STRUCTURE TYPE 1	(108A) WEARING SURFACE 2		
(108B) DECK MEMBRANE 0	(108C) DECK PROTECTION 0		
AGE OF SERVICE		LOAD RATING AND POSTING	
(27) YEAR BUILT 1967	(106) YEAR RECONSTRUCTED 1990	(31) DESIGN LOAD	6
(42) TYPE OF SERVICE ON 1 UNDER 5		(63) METHOD USED TO DETERMINE OPERATING RATING	1
(28) LANES ON 02 UNDER 00		(64) OPERATING RATING	60.0
(29) AVERAGE DAILY TRAFFIC 43957	(19) BYPASS DETOUR LENGTH 1	(65) METHOD USED TO DETERMINE INVENTORY RATING	1
(30) YEAR OF AVERAGE DAILY TRAFFIC 2014		(66) INVENTORY RATING	36.0
(109) AVERAGE DAILY TRUCK TRAFFIC 1		(70) BRIDGE POSTING	5
		(41) STRUCTURE OPEN/POSTED/CLOSED	A
GEOMETRIC DATA		APPRAISAL	
(48) LENGTH OF MAX SPAN (ft.) 30	(49) STRUCTURE LENGTH (ft.) 210	(67) STRUCTURAL EVALUATION	6
(50) CURB/SIDEWALK WIDTHS (ft.) LEFT 0 RIGHT 0		(68) DECK GEOMETRY	7
(51) BRDG RDWY WIDTH CURB-TO-CURB (ft.) 40.0		(69) UNDERCLEARANCES, VERTICAL & HORIZONTAL	N
(52) DECK WIDTH, OUT-TO-OUT (ft.) 43		(71) WATERWAY ADEQUACY	6
(32) APPROACH ROADWAY WIDTH (ft.) 40.0		(72) APPROACH ROADWAY ALIGNMENT	8
(33) BRIDGE MEDIAN 0 (34) SKEW (DEG.) 0		(36) TRAFFIC SAFETY FEATURE	
(35) STRUCTURE FLARED 0 (10) INV RTE, MIN VERT CLEAR (ft.) 99.99		36A) BRIDGE RAILINGS:	1
(47) TOTAL HORIZONTAL CLEARANCE (ft.) 41.3		36B) TRANSITIONS:	1
(53) VERTICAL CLEARANCE OVER BRIDGE ROADWAY (ft.) 99.99		36C) APPROACH GUARDRAIL:	1
(54) VERTICAL UNDER CLEARANCE (ft.) N 0		36D) APPROACH GUARDRAIL ENDS:	1
(55) LATERAL UNDER CLEARANCE RIGHT (ft.) N 99.9		(113) SCOUR CRITICAL BRIDGES	5
(56) MIN LATERAL UNDER CLEARANCE (ft.) 0		SUFFICIENCY RATING 93.9	STATUS 0
PROPOSED IMPROVEMENTS		CLASSIFICATION	
(75A) TYPE OF WORK PROPOSED	(75B) WORK DONE BY	(112) NBIS BRIDGE LENGTH	Y
(76) LENGTH OF STRUCTURE IMPROVEMENT (ft.) 0		(104) HIGHWAY SYSTEM OF THE INVENTORY ROUTE	1
(94) BRIDGE IMPROVEMENT COST (\$)	0	(26) FUNCTIONAL CLASSIFICATION OF INVENTORY ROUTE	01
(95) ROADWAY IMPROVEMENT COST (\$)	0	(100) STRAHNET HIGHWAY DESIGNATION	1
(96) TOTAL PROJECT COST	0	(101) PARALLEL STRUCTURE DESIGNATION	L
(97) YEAR OF IMPROVEMENT COST ESTIMATE	0000	(102) DIRECTION OF TRAFFIC	1
(114) FUTURE ADT 16327	(115) YEAR OF FUTURE ADT 2028	(103) TEMP STRUCTURE	
		(105) FEDERAL LANDS HIGHWAYS	0
		(110) DESIGNATED NATIONAL NETWORK	1
		(20) TOLL	3
		(21) MAINTENANCE RESPONSIBILITY	01
		(22) OWNER	01
		(37) HISTORICAL	5
		NAVIGATION DATA	
		(38) NAVIGATION CONTROL	0
		(111) PIER OR ABUTMENT PROTECTION	1
		(39) NAV VERT CLEARANCE (ft.)	0
		(116) MIN NAVIGATION VERT CLEARANCE, VERT LIFT BRIDGE (ft.)	0
		(40) NAV HORIZONTAL CLEARANCE (ft.)	0

Inspector:

Structure Number: A5020

Inspection Date:

Facility Carried: I 30, WB-13-52.27

Bridge Inspection Report

Maintenance Needs

Date Reported: 2/26/2013 12:00:00 AM

Priority: G - General/ Preventive maintenance

Work Code:

Deficiency Description:

JOINTS AT BENTS 1 AND 8 JOINTS NEEDS
TO BE FILLED. COULD CAUSE EROSION UNDER
APPROACH SLAB.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Assigned



PHOTO 1 Description Bent 1 Joint bad

Stage: Assigned



PHOTO 2 Description End of bridge joint..

Inspector:

Inspection Date:

Structure Number: A5020

Facility Carried: I 30, WB-13-52.27

Bridge Inspection Report

Maintenance Needs

Stage: Assigned



PHOTO 3 Description Joint bad ...

Inspector:

Structure Number: A5020

Inspection Date:

Facility Carried: I 30, WB-13-52.27

Bridge Inspection Report

Maintenance Needs

Date Reported: 2/26/2013 12:00:00 AM

Priority: G - General/ Preventive maintenance

Work Code:

Deficiency Description:

CONCRETE DECK CRACKS IN ALL SPANS
LARGE SEALABLE DECK CRACKS IN 2" THIN
CONCRETE OVERLAY.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Assigned



PHOTO 1 Description Span 2 crack

Stage: Assigned



PHOTO 2 Description Sealable deck cracks...

Inspector:

Structure Number: A5020

Inspection Date:

Facility Carried: I 30, WB-13-52.27

Bridge Inspection Report

Maintenance Needs

Date Reported: 2/26/2013 12:00:00 AM

Priority: G - General/ Preventive maintenance

Work Code:

Deficiency Description:

CONCRETE DECK AT BT. # 1 OLD PATCH IS
BRAKING UP.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Assigned



PHOTO 1 Description Patch area span 1