

Bridge Inspection Report

04380
CR 47-C (911=905)
over
MURRAY CREEK



Inspection Date:

Inspected By:

Inspection Type(s):

Inspector:

Structure Number: 04380

Inspection Date:

Facility Carried: CR 47-C (911=905)

Bridge Inspection Report

Location Map



Latitude: 35.83585229520992

Longitude: -90.59743793948485

Inspector:


Structure Number: 04380

Inspection Date:

Facility Carried: CR 47-C (911=905)

Bridge Inspection Report

Location Map



Latitude: 35.83585229520992

Longitude: -90.59743793948485

Inspector:


Structure Number: 04380

Inspection Date:

Facility Carried: CR 47-C (911=905)

Bridge Inspection Report

Location Map



Latitude: 35.83585229520992

Longitude: -90.59743793948485

Inspector:

Structure Number: 04380

Inspection Date:

Facility Carried: CR 47-C (911=905)

Bridge Inspection Report

Location Map



Latitude: 35.83585229520992

Longitude: -90.59743793948485

Inspector:

Structure Number: 04380

Inspection Date:

Facility Carried: CR 47-C (911=905)

Bridge Inspection Report

Maintenance Needs

Date Reported: 09/16/2019

Priority: C - Important

Work Code:

Deficiency Description:

Bent 4 abutment and wings are undermined on Lt and Rt ends up to 2' below and 3' back under.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Inspector:

Structure Number: 04380

Inspection Date:

Facility Carried: CR 47-C (911=905)

Bridge Inspection Report

Maintenance Needs

Date Reported: 09/18/2019

Priority: C - Important

Work Code:

Deficiency Description:

Approach roadways have settlement at each end of bridge. Approaches have cracks, potholes and a few patched areas.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Forward Local



PHOTO 1 Description Approach roadway

Inspector:

Structure Number: 04380

Inspection Date:

Facility Carried: CR 47-C (911=905)

Bridge Inspection Report

Maintenance Needs

Date Reported: 09/16/2019

Priority: C - Important

Work Code:

Deficiency Description:

Asphalt wearing surface has transverse and longitudinal cracks over joints between units.

Work Description:

Date Repairs Completed:

Maintenance Comments:
