

JOB A30046
TEXARKANA VISITOR CENTER – EAST (PVM.T. REPAIRS) (S)
AUGUST 12, 2026

Question:

In the quantities of the “Portland Cement Concrete Pavement Rehabilitation” there is a column that states “ number of panels”. Is the intent to remove full panels as they lay in between the existing joints or remove halves of two adjoining panels to come up with the “1” Panel? This information will help the bidders qualify what type of joints will be needed per the “Special Details for Portland Cement Concrete Pavement Patching” page.

Answer:

Regarding the "Number of Panels" column:

- A value of 1 indicates that the entire existing panel is to be removed and replaced from joint to joint.
- A value of $\frac{1}{2}$ indicates that only half of the existing panel is to be replaced. In these cases, a new joint should be constructed at the midpoint of the existing panel.
- A value of 2 indicates that two adjacent existing panels are to be removed and replaced in their entirety, adjoining each other in a multi-panel long replacement.