

Br. No. 21033 – 10/7/2015 Inspection Notes

Deck:

Transverse crack to deck to Unit 5 @ Span 1.

Transverse crack to deck to Units 3 & 5 @ Span 3.

A few minor spalls to joints between units.

Superstructure

Spalls w/ 1.5' rebar exposed to diaphragm & 2' rebar exposed to girder to Unit 1 @ Span 1.

Minor spalls to girders of Units 2 and 4 @ Span 1

Spalls w/ .5' rebar exposed to Unit 5 @ Span 1

Spall w/ 2' rebar exposed to diaphragm to Unit 7 @ Span 1.

Spalls w/ .5' rebar exposed to each end of girder at Units 1 and 7 @ Span 2

Minor spall to girder at Unit 5 @ Span 2

Spall w/ 1' rebar exposed to girder at Unit 4 @ Span 3