

Br No 14351 - 2/21/17 Inspection Notes

Deck Inspection

DECK / SLAB - MINOR VERTICAL CRACKING IN SLAB OVER PIER WALL.
MINOR CRACKING IN SOFFIT.

Superstructure

None

Substructure

MASONRY ABUTMENT - MINOR CRACKING IN MORTAR JOINTS.
MASONRY PIER WALL - MINOR CRACKING IN MORTAR JOINTS. STONE
MISSING FROM TOP OF PIER WALL ON RT. END.

CHANNEL: GRAVEL & ROCK - NO SCOUR.