

ARKANSAS DEPARTMENT OF TRANSPORTATION

Accessibility Barriers to Public Buildings and Facilities

Location	ADA Compliance Observation
District 1	
Resident Engineer Office #11	No accessible parking
West Helena AR	Restroom and access non-compliant
Resident Engineer Office #13	accessible parking paint is faded
Wynne AR	Restroom and access non-compliant
Resident Engineer Office #14	No accessible parking
West Memphis AR	Steps at both entrances (no ramp or sloped sidewalk)
	Both entry doors have round door knobs
	Restroom non-compliant (no grab bars at or near toilet, no knee guards under sink)
Welcome Center	Restroom doors exceed 5lb push/pull and 5 sec close
Helena/West Helena AR	Coffee bar exceeds maximum 34" counter height
	No accessible computer kiosk
	Accessible parking exceeds 2% maximum slope
	Need additional truncated domes where accessibility route crosses traffic pattern
Welcome Center	Restroom doors exceed 5lb push/pull and 5 sec close
West Memphis AR	Coffee bar exceeds maximum 34" counter height
	No accessible computer kiosk
	Accessible parking exceeds 2% maximum slope
	Need additional truncated domes where accessible route crosses traffic pattern
Rest Area (eastbound)	Restroom doors stick
Forrest City AR	Toilet stalls too narrow for wheelchair
	Need curb ramp in lieu of asphalt ramp
Rest Area (westbound)	No accessible route from parking to sidewalk
Forrest City AR	Accessible route to building exceeds maximum 5% running slope
	Accessible route to vending area exceeds maximum 5% running slope
	Restroom doors stick
	Toilet stalls too narrow for wheelchair
District 2	
Resident Engineer Office #21	No accessible parking
Monticello AR	No grab bars at or near the toilet in restroom
	No clearance under sink basin; vanity base with sink top
Resident Engineer Office #23	Under construction; currently using non-accessible modular building
Pine Bluff AR	
Resident Engineer Office #24	No accessible parking

Location	ADA Compliance Observation
McGehee AR	No grab bars at or near the toilet in restroom
	No clearance under sink basin; vanity base with sink top
	Mirror higher than 40 inches at bottom of reflective surface
Welcome Center	Restroom doors exceed 5lb push/pull
Lake Village AR	No accessible computer kiosk
District 3	
Resident Engineer Office #31	Restroom non-compliant
Nashville AR	
Resident Engineer Office #32	Restroom non-compliant
Hope AR	
Resident Engineer Office #34	No accessible restroom
Texarkana AR	
Rest Area	Accessible parking exceeds maximum 2% slope
Glenwood	Tripping hazards along accessible routes; ¼" max elevation change
	Accessible route to picnic pavilion exceeds maximum 5% running slope (6.5%)
	Wrong grab bars in toilet stalls
	Drinking fountain spout exceeds 36" maximum height
Welcome Center	Accessible route to building exceeds maximum 5% running slope
Texarkana AR (I-30 East)	East parking exceeds maximum 2% slope
	No accessible computer kiosk
	Coffee bar exceeds maximum 34" height
	Restroom doors exceed maximum 5lbs push/pull force and 5 second close rate
	Front entry doors stick
Welcome Center	Parking exceeds maximum 2% slope
Texarkana AR (Hwy 71)	Restroom doors exceed maximum 5lbs push/pull force and 5 second close rate
District 4	
Resident Engineer Office #41	Restroom non-compliant
Waldron AR	
Resident Engineer Office #43	Restroom non-compliant
Fayetteville AR	
Rest Area (westbound)	Sink does not have required knee clearances
Ozark AR	
Rest Area (eastbound)	No truncated domes at end of curb ramp
Ozark AR	Sink does not have required knee clearances
Rest Area	Accessible route to building exceeds maximum 5% running slope
Waldron AR	Accessible route to picnic pavilion exceeds maximum 5% running slope

Location	ADA Compliance Observation
	Accessible route to building too narrow (48")
Welcome Center	Restroom doors exceed 5lb push/pull
Van Buren AR	No accessible computer kiosk
	Coffee bar counter top at 36"
District 5	
District Headquarters	Entrance ramp too steep
Batesville AR	
Resident Engineer Offices #52 & #53	No designated accessible parking area
Batesville AR	Urinal too close to toilet
Resident Engineer Office #55	No designated disability parking space
Searcy AR	Step at the front entry door (no ramp)
	Entry door has round door knob
	Restroom doorway too narrow
	Sink does not have required knee clearances
	No grab bars at or near the toilet in restroom
Rest Area - Salado Creek	Parking exceeds 2% maximum slope; no signage
Batesville AR	No accessible picnic table
	Urinal rim height exceeds 17"
	Center line of toilet paper holder exceeds 8" from lip of toilet
	Adjust door so it closes in 5 seconds from 90 degrees
District 6	
District Headquarters	Restroom needs knee guards
Little Rock AR	
Resident Engineer Office #62	No designated disability parking area
Little Rock AR (Shamburger Lane)	
Resident Engineer Office #65	Parking area needs paint
Little Rock AR (Mabelvale Pike)	No designated unloading zone
	Restroom doorway too narrow
	Urinal needs to be removed
	No knee guards under sinks
	No grab bars around toilet
	Water fountain is cabinet-style; no leg clearance
Rest Area	Accessible route to facility exceeds maximum 5% running slope
White River (eastbound)	Accessible picnic pavilion isn't labeled
Rest Area	Accessible parking exceeds maximum 2% slope
White River (westbound)	

Location	ADA Compliance Observation
Rest Area	Needs additional accessible picnic table
Social Hill (Malvern AR)	
District 7	
Resident Engineer Office #73	No accessible restroom
Camden AR	No accessible parking
	No approach and entrance points
Resident Engineer Office #73 Sub-Office	Restroom non-compliant
Arkadelphia AR	No accessible parking space or approach
Resident Engineer Office #74	Restroom non-compliant
Camden AR	
Rest Area (westbound)	Needs accessible parking sign
Gurdon AR	Needs paint/stripping
	Needs truncated domes at curb ramp
	Tripping hazards on accessible routes to vending and picnic table
	Gaps at sidewalks along accessible routes
	Accessible picnic shelter no labeled
	Unlevel sidewalk at picnic shelter
	Toilet stall not accessible (2'-10" wide)
Rest Area (eastbound)	Parking exceeds maximum 2% slope
Gurdon AR	Need curb ramp in lieu of asphalt ramp
	Accessible route to vending and picnic shelter exceeds maximum 5% running slope
	Toilet stalls not accessible
Welcome Center	Accessible parking exceeds maximum 2% slope
El Dorado AR	Accessible route to building exceeds maximum 5% running slope
	No accessible computer kiosk
	Coffee bar exceeds maximum 34" counter height
	Restroom doors exceed 5lb push pull and 5 sec. close
District 8	
Resident Engineer Office #82	No accessible restroom
Clarksville AR	No accessible parking and approach
Resident Engineer Office #84	No accessible restroom
Conway AR	No accessible parking and approach
Resident Engineer Office #86	No accessible restroom
Russellville AR	No accessible parking and approach
Rest Area (westbound)	Accessible route to picnic pavilion exceeds maximum 5% running slope
Big Piney	Accessible parking needs paint

Location	ADA Compliance Observation
Rest Area (eastbound)	Accessible route exceeds maximum 5% running slope
Big Piney	Accessible parking needs paint
District 9	
District Headquarters	Restroom non-compliant
Harrison AR	
Resident Engineer Office #92	No accessible restroom
Harrison AR	No accessible parking and approach
Resident Engineer Office #94	No accessible restroom
Bentonville AR	No accessible parking and approach
Resident Engineer Office #95	No accessible restroom
Flippin AR	No accessible parking and approach
Welcome Center	Accessible route to building exceeds 5% running slope
Bella Vista AR	Accessible parking exceeds 2% slope
Welcome Center Siloam Springs AR	<p>No accessible route to after-hours entrance</p> <p>Need accessible parking signage</p> <p>Accessible route to building too narrow</p> <p>Reception counter not accessible</p> <p>No accessible computer kiosk</p> <p>Coffee bar not accessible</p> <p>Not enough clear floor space around information kiosks (pamphlets)</p> <p>Swinging doors between restrooms and lobby not accessible</p> <p>Toilet stalls too narrow</p> <p>Restroom doors exceed maximum 5lbs push/pull force and 5 second close rate</p>
Welcome Center	Accessible parking at building and picnic shelter exceeds 2% maximum slope
Harrison AR	Restroom doors exceed maximum 5lbs push/pull force and 5 second close rate
District 10	
Resident Engineer Office #04	No designated parking area
Paragould AR	Restroom non-compliant
Resident Engineer Office #05	No designated parking area
Osceola AR	Step at front entrance (no ramp)
	Restroom non-compliant
Resident Engineer Office #06	No designated parking area
Jonesboro AR	Step at front entrance (no ramp)
Welcome Center	No accessible computer kiosk
Blytheville AR	Coffee bar exceeds maximum 34" height
	Restroom doors exceed maximum 5lbs push/pull force and 5 second close rate

Location	ADA Compliance Observation
	Parking needs repainting/stripping
Welcome Center	Accessible route to building exceeds maximum 5% running slope
Corning AR	Parking exceeds maximum 2% slope
	Accessible route to picnic pavilion exceeds maximum 2% cross slope
	No accessible computer kiosk
	Coffee bar exceeds maximum 34" height
	Restroom doors exceed maximum 5lbs push/pull force and 5 second close rate
Rest Area	Parking exceeds 2% maximum slope
Imboden/Blackrock	Accessible route exceeds maximum 5% running slope
	Accessible route to picnic exceeds maximum 2% cross slope
	Toilet stalls non-compliant
Central Office	
Equipment & Procurement Annex	Restroom non-compliant