



NOTE: Channel beams are not transversely bolted.

*Not to Scale

Bridge No. 20917	Dist. 5	Co. Independence - 32
Logmile 0.15	Rt. 00070	Sect/Zone - 00/E
Date Drawn 02/07/2017	By NSE	