

Bridge Inspection Report

00433
US 67-20- LM 8.40
over
OAK CR



Inspection Date:

Inspected By:

Inspection Type(s):

Inspector:

Structure Number: 00433

Inspection Date:

Facility Carried: US 67-20- LM 8.40

Bridge Inspection Report

National Bridge Inventory

IDENTIFICATION		INSPECTIONS	
(1) STATE CODE	056 - Arkansas	(90) INSPECTION DATE	2/4/2015
(8) STRUCTURE NUMBER	00433	(91) DESIGNATED INSPECTION FREQUENCY	24
(5) INV. ROUTE (ON/UNDER)	1 2 1 67 0	(92) CRITICAL FEATURE INSPECTION	(93) CFI DATE
(2) HIGHWAY AGENCY	10 (3) COUNTY CODE 021	A. FRACTURE CRITICAL DETAIL	N
(4) PLACE CODE	00000	B. UNDERWATER INSPECTION	N
(6) FEATURES INTERSECTED	OAK CR	C. OTHER SPECIAL	N
(7) FACILITY CARRIED	US 67-20- LM 8.40		
(9) LOCATION	2.5 MI W OF CORNING, ARK		
(11) MILEPOINT 8.400	(12) BASE HIGHWAY NETWORK 1		
(13A) LRS INVENTORY ROUTE	0000067200 (13B) SUBROUTE NUMBER 00		
(16) LATITUDE 36.41165075798725	(17) LONGITUDE -90.63359615780405		
(98A) BORDER BRIDGE CODE			
PERCENT RESPONSIBILITY	(99) BORDER BRIDGE STRUCT		
STRUCTURE TYPE AND MATERIAL		CONDITION	
(43) STRUCTURE TYPE, MAIN		(58) DECK	7
A) KIND OF MATERIAL/DESIGN: 1 - Concrete		(59) SUPERSTRUCTURE	7
B) TYPE OF DESIGN/CONSTR: 04 - Tee Beam		(60) SUBSTRUCTURE	7
(44) STRUCTURE TYPE, APPROACH SPANS		(61) CHANNEL & CHANNEL PROTECTION	5
A) KIND OF MATERIAL/DESIGN: 0 - Other		(62) CULVERT	N
B) TYPE OF DESIGN/CONSTR: 00 - Other			
(45) NUMBER OF SPANS IN MAIN 2	(46) NUMBER OF APPROACH 0		
(107) DECK STRUCTURE TYPE 1	(108A) WEARING SURFACE 6		
(108B) DECK MEMBRANE 0	(108C) DECK PROTECTION 0		
AGE OF SERVICE		LOAD RATING AND POSTING	
(27) YEAR BUILT 1928	(106) YEAR RECONSTRUCTED 1954	(31) DESIGN LOAD	4
(42) TYPE OF SERVICE ON 1	UNDER 5	(63) METHOD USED TO DETERMINE OPERATING RATING	1
(28) LANES ON 02	UNDER 00	(64) OPERATING RATING	60.0
(29) AVERAGE DAILY TRAFFIC 3600	(19) BYPASS DETOUR LENGTH 4	(65) METHOD USED TO DETERMINE INVENTORY RATING	1
(30) YEAR OF AVERAGE DAILY TRAFFIC 2014		(66) INVENTORY RATING	36.0
(109) AVERAGE DAILY TRUCK TRAFFIC 1		(70) BRIDGE POSTING	5
GEOMETRIC DATA		(41) STRUCTURE OPEN/POSTED/CLOSED	A
(48) LENGTH OF MAX SPAN (ft.) 29.4	(49) STRUCTURE LENGTH (ft.) 58.8		
(50) CURB/SIDEWALK WIDTHS (ft.) LEFT 1.5	RIGHT 1.5		
(51) BRDG RDWY WIDTH CURB-TO-CURB (ft.)	28		
(52) DECK WIDTH, OUT-TO-OUT (ft.)	33.5		
(32) APPROACH ROADWAY WIDTH (ft.)	38.1		
(33) BRIDGE MEDIAN 0	(34) SKEW (DEG.) 30		
(35) STRUCTURE FLARED 0	(10) INV RTE, MIN VERT CLEAR (ft.) 99.99		
(47) TOTAL HORIZONTAL CLEARANCE (ft.)	28.2		
(53) VERTICAL CLEARANCE OVER BRIDGE ROADWAY (ft.)	99.99		
(54) VERTICAL UNDER CLEARANCE (ft.)	N 0		
(55) LATERAL UNDER CLEARANCE RIGHT (ft.)	N 99.9		
(56) MIN LATERAL UNDER CLEARANCE (ft.)	0		
PROPOSED IMPROVEMENTS		APPRAISAL	
(75A) TYPE OF WORK PROPOSED	(75B) WORK DONE BY	(67) STRUCTURAL EVALUATION	7
(76) LENGTH OF STRUCTURE IMPROVEMENT (ft.) 0		(68) DECK GEOMETRY	4
(94) BRIDGE IMPROVEMENT COST (\$)	0	(69) UNDERCLEARANCES, VERTICAL & HORIZONTAL	N
(95) ROADWAY IMPROVEMENT COST (\$)	0	(71) WATERWAY ADEQUACY	8
(96) TOTAL PROJECT COST	0	(72) APPROACH ROADWAY ALIGNMENT	8
(97) YEAR OF IMPROVEMENT COST ESTIMATE		(36) TRAFFIC SAFETY FEATURE	
(114) FUTURE ADT 4221	(115) YEAR OF FUTURE ADT 2028	36A) BRIDGE RAILINGS:	0
		36B) TRANSITIONS:	0
		36C) APPROACH GUARDRAIL:	0
		36D) APPROACH GUARDRAIL ENDS:	0
		(113) SCOUR CRITICAL BRIDGES	5
		SUFFICIENCY RATING	0
		STATUS	78.7
		CLASSIFICATION	
		(112) NBIS BRIDGE LENGTH	Y
		(104) HIGHWAY SYSTEM OF THE INVENTORY ROUTE	1
		(26) FUNCTIONAL CLASSIFICATION OF INVENTORY ROUTE	02
		(100) STRAHNET HIGHWAY DESIGNATION	0
		(101) PARALLEL STRUCTURE DESIGNATION	N
		(102) DIRECTION OF TRAFFIC	2
		(103) TEMP STRUCTURE	
		(105) FEDERAL LANDS HIGHWAYS	0
		(110) DESIGNATED NATIONAL NETWORK	1
		(20) TOLL	3
		(21) MAINTENANCE RESPONSIBILITY	01
		(22) OWNER	01
		(37) HISTORICAL	5
		NAVIGATION DATA	
		(38) NAVIGATION CONTROL	0
		(111) PIER OR ABUTMENT PROTECTION	5
		(39) NAV VERT CLEARANCE (ft.)	0
		(116) MIN NAVIGATION VERT CLEARANCE, VERT LIFT BRIDGE (ft.)	0
		(40) NAV HORIZONTAL CLEARANCE (ft.)	0

Inspector:

Structure Number: 00433

Inspection Date:

Facility Carried: US 67-20- LM 8.40

Bridge Inspection Report

Element Inspection

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
16 - Reinforced Concrete Top Flange	1- Ben.	2010	sq. ft.	2010			
510 - Wearing Surfaces		1680	sq. ft.	1680			
110 - Reinforced Concrete Open Girder/Beam	1- Ben.	367	ft.	367			
205 - Reinforced Concrete Column	1- Ben.	5	each	5			
215 - Reinforced Concrete Abutment	1- Ben.	131	ft.	131			
234 - Reinforced Concrete Pier Cap	1- Ben.	36	ft.	36			
333 - Other Bridge Railing	1- Ben.	120	ft.	120			