



View of bents
from channel



Splice Details
Splices located 15.3' & 41.0' from B+1



Interior Girder Detail

