



SIDE VIEW



CROSS SECTION BENTS #2,3



CROSS SECTION ABUTMENT #2

CROSS SECTION ABUTMENT #1 SAME AS ABUTMENT #2 BUT PILES AND BACKWALL COMPLETELY UNDER DIRT