






# Br. M3801

## Hempstead County Rt.278 LM- 3.54





### SUBSTRUCTURE

R.C Caps With Timber Piles



### PRECAST CHANNEL BEAM UNITS



Note: Piles at both Bents 1 & 4 are not  
Visible due to piles being underground  
Measurements & Condition are *ESTIMATED*