



Br. M2999

Profile
Shots taken at
curb top
EJW&JPW
09222020









BRIDGE INSPECTION REPORT
FORM III

Inspected By: EJW&JPW

Date: 09222020

District: 4 Co.: Polk Rte.: 375 Sect/Zone 1 Log Mile: 4.29 Str. No.: M2999