




# Cross Section View of Bridge (Seven Pre-cast or Pre-stressed Units) Curbs and Guard Rail



## Cross Section View of Unit



## Side View of Unit


Insp. CEV-RSDate 1-31-2001Dist. 7Co. CLARKRt. 7Sec. 6Log 6.53Br. No. M0178

1/4


BRIDGE INSPECTION REPORT — FORM III




Bent 4




Bent 3



Bent 2



Bent 1

Insp. CEV. RS


## BRIDGE INSPECTION REPORT — FORM III

Date 1-31-2001Dist. 7Co. CLARKRt. 7Sec. 6Log 6.53Br. No. MO178


3/4




Bent 8




Bent 7



Bent 6



Bent 5



Insp. CEV-RS.

SCS-2-10-05  
Rev B7B

BRIDGE INSPECTION REPORT — FORM III


Date 1-31-2001

Dist. 7 Co. CLARK Rt. 7 Sec. 6 Log 6.53 Br. No. M0178


3/4




Bent 12




Bent 11



Bent 10



Bent 9

Insp. CEV. RS.

BRIDGE INSPECTION REPORT — FORM III

4/4

Date 1-31-2001Dist. 7 Co. CLARK Rt. 7 Sec. 6 Log 6.53 Br. No. M0178