

NBIS RATING	DESCRIPTION	S	E	QTY	UNITS	QUANTITY IN CONDITION STATE				
						1	2	3	4	
6	DECK									
38	R/C SLAB W / 2" ACHM OVERLAY	F	M	576	SF	576				
	RAIL									
	JOINTS									
6	SUPERSTRUCTURE									
	R/C SLAB									
6	SUBSTRUCTURE									
211	MASONRY PIER WALL	F	M	28	LF		28			
217	MASONRY ABUTMENTS	F	M	56	LF		56			
7	CHANNEL									
	GRAVEL & ROCK - NO SCOUR.									
7	WATERWAY ADEQUACY			BEGINNING POSTING						
				ENDING POSTING						

DESCRIPTION REQUIRED ON ALL ELEMENTS IN CONDITION STATE 3,4 OR 5 (SPAN, LOCATION, SEVERITY, ETC.) AND ALL SMART FLAGS

ELEM.	DESCRIPTIONS
38	DECK / SLAB - MINOR VERTICAL CRACKING IN SLAB OVER PIER WALL. MINOR CRACKING IN SOFFIT.
211	PIER - MINOR CRACKING IN MORTAR JOINTS. STONE MISSING FROM TOP OF PIER WALL ON RT. END.
217	ABUTMENT - MINOR CRACKING IN MORTAR JOINTS.